G. R. S. 58]

Previous references.
Genl 322-21-1-6

1924
(Confdl)

File No. 149-24
Serial Nos. 1—2

Later references
Genl. 149-74-324

GENERAL AND REVENUE SECRETARIAT.

Serial Nos. 2

Part B for January 1925

SUBJECT

Submits for sanction an estimate for Rs 2740/- for repairing the Sri Hiranat Gopalaswamy temple on the hill near Gundlupet

If D. No 977-9 dated 7.1.25

To the Secy. Comr
" Chief Engr
" Comptr

Sanctioned

B170

F. R. S. 11] 1924-25

GENERAL AND REVENUE SECRETARIAT.

(Mwr

NOTES.

File No. 149-24

FILE HEADING

Repairs to the Sri Hariharar Gopalaswami temple at Gundlupet.

From

The Chief Engineer

No. 8102 Dated 22.11.24 Received 1.12.24

Diary No. 788.	Enclos 1 file	Spare Copies -	Serial No. 1

BRIEF ABSTRACT OF LETTER.

Submits for sanction an estimate for Rs 2740/- for the repairs of Sri Gopalaswami temple at the title the charge being met from the State Grant or Interest earnings (Thogai No 2

NOTES AND ORDERS.

1) Mwr File 322-24 put up for reg^d deals with an Estimate of Rs 3410 prepared for the repairs of this temple which was kept pending in 1921-22. The Dy Mwr Con^r was informed in this office letter No 1786-B/ 18.9.22 that the State Grant allotment had almost been exhausted. The

NOTES—First Sheet.

G. R. S. III-2]

General and Revenue Secretariat.

Mdu—File No. 149 of 1924

Serial No

might get revised estimates prepared for the repairs of the temple which might be dealt with in instalments in the order of urgency.

2) The Executive Engr. has now submitted an estimate for Rs 2740/- for the repairs of the temple. And say that the estimate was inspected by the Ex. Engr. & that all the items of work provided for in the estimate are reqd.

3) May the Govt be pleased to direct the Govt being met from the interest earning of the Genl Mdu Fd, as there is no budget provision for the State Grant allotted

Sd
1/12/24

4) Is there no money at the credit of this institution?

Para 1) 1/12.

5) Reference is invited to the Dy Comrs letter WRC 93 dt 28.6.24 to the Mdu Comr stating that there is only a sum of Rs 830 odd at its credit and that this cannot be used towards the repairs on a large scale as the institn ought to be left with some money for any incidental charges"

Sd
2/12/24

6) Mean bus up
2.12.

NOTE—Contn. sheet

SF 2/12

7) In the statement of works to be [illegible] grant assistance from the Interest Earnings of the Sinking Fund the Mun Cmr has included 2750 Rs for grain to this institution. This staff is putting with the file relating to the Mariyala Yogeshwara Swamy temple repairs.

Respondent sanctions the estimate & submits for appl & orders

8/12/26

9) Pr appl

3.12.26.

Rev-Secy

22/5/27 II

Secy

5.12.26.

10) Draft order sanctioning the estimate for appr

26/2

11) [illegible]

Pl

Secy

Dft file is placed below (Flag K)

9/12

Serial No.	
1	To The Chief Engineer of Mysore, Bangalore & Kempthollow. No. 977-9 dt. 7.1.25. Sanctions the estimate for Rs. 2760, the charge being from the allotment of Rs. 10,000 out of the interest earnings of the Govt Munzrai fund for the repairs of wells.
	" Munzrai Secy to H.H. No. 980 dt. 7.1.25. Forwarding copy of the above for info.

14/1/25

File No. of 19 .

General and Revenue Secretariat.

Serial No.	

NOTE—Contn. Sheet

2 999

WD 1576-GPB—5,000—25-1-23

NO. 8102 / 1924

MYSORE PUBLIC WORKS DEPARTMENT,
CENTRAL OFFICE,
Dated Bangalore 28 November 1924.



FROM John Bhore, Esq., A.M.I.C.E.,
Chief Engineer of Mysore, Bangalore.



To

H.V.Anantharaman, Esq., B.A., Muz.149-24-1.
Secretary to Government, Revenue Department,
Bangalore.

SIR,

With reference to your letter No.1286/Muz.322-21-6 dated the 18th September 1922, to the address of the Muzrai Commissioner in Mysore, I have the honor to forward herewith a revised estimate - amounting to Rs.2,740/- (as corrected in this office) for repairing the Sri Himavat Gopalaswami Temple on the hill near Gundlupet.

2. The revised estimate now forwarded has been prepared by the Executive Engineer, Mysore Division, in consultation with the Deputy Commissioner, Mysore District.

3. While transmitting the estimate, ~~to~~ the Muzrai Commissioner has stated that the institution was inspected by the Execu. Engineer and all the items of work now proposed and provided for i the present revised estimate are quite necessary. The Amildar and the Sub Division Officer who inspected the building are also of the same opinion.

4. As regards funds for the work, the Deputy Commissioner for reasons given in his letter No.R.C.93/23-24 dated the 28th June 1924 (copy enclosed) states that the cost may be met out of the State Grant allotment or from the interest earnings of the General Muzrai Fund. The Muzrai Commissioner in Mysore supports the recommendation.

5. The file of correspondence on the subject received from the Muzrai Commissioner is also herewith forwarded for information and perusal.

I have the honour to be,

S i r,

Your most obedient servant,

27.11.24

HRR.2/26th.

Chief Engineer of Mysore.

Letter No.R.C.93/23-24 dated the 10/11th January 1924, from the Deputy Commissioner, Mysore District, to the Muzrai Commissioner in Mysore.

==========

With reference to your letter No.Dl.Dis.5 of 22-23 dated the 14th October 1922, forwarding copy of Revenue Secretary's letter No. 1286/Muz.322-21-6 dated the 18th September 1922, stating that the items of work mentioned in the revised estimate for effecting certain improvements to the Sri Himavat Gopalaswamy temple on the hill near Gundlupet, may be taken up in the order of urgency and an estimate got prepared and dealt with in due course, I have the honor to submit herewith an estimate for Rs.2,750/- for necessary repairs, etc., received with the correspondence ending with Nanjangud Sub Division Officer's Memo No.R.O.C.110/20-21 dated 26-7-23. The estimate has been duly revised and prepared by the D.P.W. authorities and the report accompanying it explains the necessity for the work.

The Amildar and the Sub Division Officer after inspection of the Temple, report that all the items of work referred to in the estimate are absolutely necessary and urgent. As such, sanction may kindly be accorded to the estimate, the cost being met from the State Grant allotment for this year. I may mention that a recommendation, in this connection, has already been made, for the grant of the cost of this estimate, in this office Pet.No.187/23-24 dated 29-7-23 with which a statement showing the requirements of this District for help from State Grant towards the repairs of Muzrai Institutions was submitted. Recommendation is being sent up year after year for the ~~las~~ last three years for help from the State Grant for improving this temple, and each time, ~~and~~ the papers are being sent back with orders to renew the application next year.

Under the circumstances, I request that the estimate may kindly be sanctioned at least this year with a view to see the temple repaired and improved early.

==========

"C o p y."

S. Srinivasaiya

HRR/24tn. 27/2 for Chief Engineer of Mysore.

Letter No. R.C.93/23-24 dated 28th June 1924 from the Deputy Commissioner, Mysore District to the Muzrai Commissioner in Mysore.

"Subject:-- Retransmitting the estimate for repairing the Sri Himavat Gopalaswamy temple on the Hill at Gundlupet, duly scrutinized by the Executive Engineer.

"With reference to your letter No.C.697/23-24 dated 22nd --- January 1924 returning the estimate for certain urgent repairs to the Sri Himavat Gopalaswamy temple on the hill near Gundlupet, for ------ resubmission after scrutiny by the Executive Engineer I have the honor to state that the Executive Engineer, has, after a personal inspection of the institution found all the repairs provided for in the estimate quite necessary and urgent. The estimate has also been duly countersigned by him. A copy of the Executive Engineer's letter No.235 dated 25-2-24 returing the estimate to this office after scrutiny is herein enclosed.

2. As for the amount at the credit of the institution the Amildar reports that there is only a sum of Rs.800/- and odd at its credit and that this cannot be used towards this repairs on a large scale as the institution will be left without any money afterwards for any incidental charges that are likely to arise from time to time.

3. Therefore, the amount of estimate may kindly be entirely met out of the State Grant allotment or from the interest earnings of the General Muzrai Fund. The Executive Engineer is also of the same --- opinion. The importance of this institution need hardly be pointed out in support of the recommendation.

4. The connected file of vernacular papers received with your - letter under reference is retransmitted herewith."

"Copy"

For Muzrai Commissioner.

KSR.

Mur. 7]

SUBJECT.... .....

... .

....

Diary No of letter replied to... 7867

SECTION Mur

FILE No. 149-24

SERIAL No. 1.

Murai Secretariat

( )

the 192 .

Proceedings of the Government of
His Highness the Maharaja of Mysore

Date of issue 7. 1. 25

Signed by. M. T. P.

Read—

Correspondence ending with letter no 8102 dated the 28th November 1924 from the Chief Engr of Mysore submitting for sanction an estimate of Rs 2,740 for repairing the Sri Hariharesvara & Balamma temples on the hill near Sundrapet & stating that ~~the Order Thereon No.~~ the building was inspected by the Exec Officer & Sup Engr

May this be

i Printed ?

ii treated as a standing order ?

iii published in the Gazette. English Part ?

iv translated ?

v placed at the disposal of the press ?

vi published in the Gazette, Kannada Part ?

KK 10/1

who are all of the
opinion that the ~~above~~
works mentd in the
estimate are necessary.

—

Order No 977-9/mscr 149-24-2
Encl one file & 7.1.25

The estimate for Rs 2760
is sanctioned, the charge being
met from the allotment of
10,000 Rs (cost of the Interest
earnings of the Genl Mngt Fd
~~for the purpose of Rs~~
for repairs of this Mrs in
the current Yr.

The work should be
taken in hand at once, and
completed early.

List of enclosures.

2 copies

3/12/24.

Under Secy
RL
3/12/24

To

The Chief Engr with the Secret file
& connected records

Copied by

Examined by

Mscr Comr with a copy of above Ltr

Comptroller with a copy of above Ltr — 980 & 7.1.25

Copy to Hazur Secy for info

BO

2 Under Secys

WD 0566—2000—GPB—29-7-22

Secret in Gen No
685-6/mscr 62-24
& 11+11-24

ABSTRACT OF ESTIMATE FOR repairing the Hemavathy Male Swami Temple at Gundlupet

Particulars	Per	Rate	Quantity	Cost
Dismantling and removing concrete of the roof conveying and stacking the stuff at a distance.	Cft.	6 0 0	28.40	171 0 0
Putting one layer of 3" surki concrete 2 courses of flat tiles in surki mortar and plastered over with cement &c. complete.	Sqr.	50 0 0	28.44	1422 0 0
. Earthwork excavation.	cft.	1 8 0	1.35	2 0 0
. Size stone in surki mortar.	"	50 0 0	3.78	189 0 0
. Surki mortar pointing	sqr.	4 0 0	3.30	13 0 0
. New zinc sheet sun shades including fixing.	each	15 0 0	12	180- 0
'. Constructing a chimney for the kitchen		L. S.		25 0 0
3. Providing new Mangalore tiles in place of broken ones	"	4	20	5 0 0
9. Teakwood main door 2½" thick with iron work, brass	sft	4 8 0	29	131 0 0
0. Removing and fixing door and window after exchanging places by dismantling old stone masonry and rebuilding the same and constructing drains.		L. S.		50 0 0
1. Supplying and fixing teakwood battened door including fixing.	"	2 0 0	15	30 0 0
2. Preparing and fixing iron gate.	"	5 0 0	50	300 0 0
*. Unforeseen items during execution.		L. S.		92 0 0
Total				2610 0 0
Contingencies at 5%				130 0 0
Grand Total				2740 0 0

Rupees two thousand seven hundred and forty only.

* C O P Y *

Superintendent, Muzrai Branch.

Sanctioned for Rs.

No. dated in Govt. Progs.

W D.024 -GPB—2,500—11-1.19